MEDICAL IMAGING
CSO Customer Support Operations

Fieldservice Bulletin

Order-No.: DD+DIS082.00E

1 Piece QLCZ0 MA1

March 2000

ADC Compact
Type 5145
ADC Solo
Type 5155

Please file this document in section 13 of your technical documentation.

New Language Floppy for ADC-Compact and ADC-Solo Version COPL1102

Classification			When?		
Safety relevant	Reliability	New function	Immediately	Next service	As required
		x			x

1 General

A floppy disk containing a new version of language files (COPL1102) for the user interface is available now. After the installation the following languages are available:
Danish, German, English, Spanish, Finnish, French, Italian, Dutch, Norwegian, Portuguese, Swedish.

Order Number:
Version COPL1102 **CM+9.5145.0923.0**

2 Hardware and Software Requirements

No special hardware requirements,
ADC-Compact Software > COP_1111,
ADC-Solo Software > SOL_1008

3 Installation

Select

```
Service Menu
        Install from floppy
                Language files.
```

Follow the online instructions.

4 Known Bugs in COPL1102

- ADC-Compact displays the ADC-Solo menu of the keyoperator after the language is fixed. This problem is gone after a reset.
- The "Destination not ready" message is not always centered properly.

5 Installation ex Works

The language files are installed ex works with the following software:

type 5155: SN ≥ 1245, 1246, 1253 – 1256, 1259, 1264, **≥ 1268**